

Figure: 30 TAC §312.129(b)

Equation F.1

$$AWAR = \frac{ACLR}{C \times 0.001}$$

Where:

ACLR = Annual cadmium loading rate in kilograms per hectare per 365-day period.

C = Cadmium concentration in milligrams per kilogram of total solids (dry weight basis).

AWAR = Annual whole application rate in metric tons per hectare per 365-day period (dry weight basis).

0.001 = A conversion factor.